

Report Summary

Report ID	CPX-1001	Inspection Type	150-Point Sample
Vehicle	2018 Toyota Camry SE	Mileage	86,420 miles
VIN	SAMPLEVIN123456789	Location Type	Dealer / Seller

Final Risk Rating:YELLOW - Proceed With Caution

Transmission, electrical, tire, and engine-bay findings should be reviewed before purchase. This sample report shows the clear condition snapshot a customer can expect.

150-Point Category Snapshot

Inspection Area	Pts	Status	Sample Notes
Exterior & Body	20	CAUTION	Body panels, paint, glass, lights, trim, and visible damage.
Interior & Safety	18	PASS	Seats, dashboard controls, mirrors, windows, and visible safety items.
Engine Bay	22	CAUTION	Fluids, leaks, belts, hoses, battery area, mounts, and visible wear.
Transmission & Drivetrain	18	CAUTION	Shift quality, drivetrain response, fluid seepage signs, and noises.
Electrical System	16	PASS	Battery/charging signs, lights, windows, locks, accessories, warning indicators.
OBD2 & Diagnostics	12	PASS	Active, pending, and stored codes when scanner access is available.
Brakes	12	REVIEW	Pedal feel, stopping behavior, visible pad/rotor condition where accessible.
Suspension & Steering	12	REVIEW	Steering feel, ride quality, noises, visible wear, and alignment clues.
Tires & Wheels	10	CAUTION	Tread signs, uneven wear, tire age clues, wheel damage, pressure warning.
Undercarriage & Frame	10	CAUTION	Leaks, rust, frame/structure visible areas, exhaust, underbody concerns.

Key Sample Findings

Status	Sample Finding & Buyer Action
PASS	Vehicle starts, idles, and basic electrical accessories respond during sample review. Continue review with road test and scan.
CAUTION	Transmission/drivetrain should be reviewed for shift quality, delay, vibration, and fluid seepage. Use this point to negotiate or request service proof.
CAUTION	Minor oil seepage visible near engine area in sample notes. Request repair estimate or follow-up before purchase.
CAUTION	Tires show uneven wear and may indicate alignment or suspension concerns. Ask seller for tire/alignment history or budget replacement.
REVIEW	Buyer should verify title, liens, auction terms, seller documents, and service records separately. Inspection is not title, legal, or warranty clearance.

What The Customer Receives

1	Clear condition snapshot with PASS / CAUTION / REVIEW labels.
2	Inspection notes organized by major systems, including transmission and electrical.
3	Photo proof page showing key areas documented during the inspection.
4	Final risk rating to help the buyer move forward, negotiate, or walk away.

Jotform Report Alignment

This sample preview is designed to match the same inspection categories that will later be collected through the private Jotform field report built by Ramon. The final PDF report generated from Jotform should use the same major sections: summary, risk rating, category results, findings, and photo proof.

Important Sample Disclaimer

This sample report is for website preview only. CARMEPX inspections are condition snapshots at the time of inspection, based on visible access, seller permission, safety, and available equipment. This is not a warranty, guarantee, title check, insurance policy, repair estimate, or promise of future vehicle performance.

Photo Proof Preview

Customers feel more confident when they can see proof. The final Jotform inspection report should include uploaded photos from the same areas shown below.

PHOTO PROOF



VIN Sticker

Confirms vehicle identity and matches customer order.

PHOTO PROOF



Odometer

Documents mileage at time of inspection.

PHOTO PROOF



Exterior Front/Rear

Shows body condition, paint, lights, and trim.

PHOTO PROOF



Interior/Dashboard

Shows cabin condition and warning lights.

PHOTO PROOF



Engine Bay

Shows fluids, leaks, belts, hoses, and battery area.

PHOTO PROOF



Transmission Area

Shows visible leaks or drivetrain concerns where accessible.

PHOTO PROOF



Electrical/Battery

Shows battery, terminals, charging signs, and related components.

PHOTO PROOF



OBD2 Scanner Screen

Shows diagnostic scan result when available.

PHOTO PROOF



Undercarriage/Tires

Shows rust, leaks, tires, brakes, and underbody concerns.

Website note: use this page as a proof-style visual preview only. The real customer report will be produced from the private Jotform inspection workflow.